

Appendix B

Flue Nozzle Repair and Replacement Plan

1. Track exceedances and corrective actions electronically along with the date that repairs were completed.
2. Repairs will be completed based on the following schedule:
 - Flue cleanout will be completed within 10 days of exceedance root cause identification;
 - Flue nozzle replacement will be completed within 21 days of exceedance root cause identification.

Days where the oven is taken out of service will not be counted.
3. Flue inspections including cross wall inspections (or equivalent technique) will be performed monthly and the results maintained electronically.
4. A procedure for prioritizing repairs will be maintained in the Environmental Management System.
5. Equivalent techniques will be approved by ACHD.