

Appendix E

Enhanced Preventive Maintenance Refractory Repair Plan

1. Perform dry gunning all oven ends.
2. Perform dry gunning all standpipe interiors.
3. Perform dry gunning all charging holes.
4. Perform ceramic welding and replace standpipes where dry gunning is not sufficient.
5. Equivalent techniques will be approved by ACHD.