

Appendix D

Gas Gun Improvement Plan

1. Cross wall data are used to identify potential gas gun issues.
2. Repairs will be completed based on the following schedule:
 - Gas gun cleanout will be completed within 10 days of exceedance root cause identification;
 - Gas gun weld will be completed within 21 days of exceedance root cause identification:
3. Repairs are documented electronically.
4. Follow-up cross wall temperatures are taken and documented electronically to track effectiveness.
5. Equivalent techniques will be approved by ACHD.