

and the plan approval issued to the source are operated and maintained in accordance with specifications in the application and conditions in the plan approval and operating permit issued by the Department. A person may not cause or permit the operation of an air contamination source subject to this chapter in a manner inconsistent with good operating practices.”

258. ArcelorMittal has been in continuous violation of Section C.VI. #022 of the Title V Permit from the date of the Plant’s re-start on April 10, 2014, by failing to install, operate, and maintain a Continuous H<sub>2</sub>S Monitoring Device of the type described in Section C.III. #015(a) of the Title V Permit.

259. ArcelorMittal’s failure to install, operate, and maintain a continuous H<sub>2</sub>S monitor of the type described in Section C.III. #015(a) of the Title V Permit constitutes a continuous violation of the CAA, from the date of the Plant’s re-start on April 10, 2014.

**COUNT VIII: Sulfur Dioxide Violations**

260. Section D.I. #001(a) of the Plant’s Title V Permit provides: “The SO<sub>x</sub> emissions (as SO<sub>2</sub>) as measured in the combined boiler exhaust stack shall not exceed 63 pounds per hour (lbs/hr) or 275 tons per year (tpy).”

261. The chart below includes complaint ¶¶ 261a-261h listing dates and emission levels of SO<sub>2</sub> per hour as measured in the combined boiler exhaust stack at the Plant:

<b>COMPLAINT PARAGRAPH NUMBER</b>	<b>DATE</b>	<b>AMOUNT EMITTED (lbs/hr SO<sub>2</sub>)</b>
261a	6/15/14	67
261b	6/20/14	117
261c	6/23/14	68
261d	7/11/14	70
261e	7/13/14	65
261f	7/14/14	80
261g	7/15/14	78
261h	7/19/14	74

261i	7/20/14	86
261j	7/21/14	74
261k	7/22/14	78
261l	7/23/14	64
261m	7/24/14	65
261n	8/20/14	106
261o	8/21/14	94
261p	8/22/14	111
261q	8/23/14	88
261r	8/24/14	78
261s	8/25/14	97
261t	8/26/14	106
261u	8/27/14	115
261v	8/28/14	118
261w	8/29/14	115
261x	8/30/14	115
261y	8/31/14	115
261z	9/1/14	128
261aa	9/2/14	130
261bb	9/3/14	119
261cc	9/4/14	107
261dd	9/5/14	105
261ee	9/6/14	122
261ff	9/7/14	119
261gg	9/8/14	127
261hh	9/9/14	113
261ii	9/10/14	125
261jj	5/19/15	83
261kk	5/22/15	183
261ll	5/28/15	119

262. ArcelorMittal violated Section D.I. #001(a) of the Plant's Title V Permit by emitting SO<sub>2</sub> as measured in the Plant's combined boiler exhaust stack in excess of 63 pounds lbs/hr. on each of the dates set forth in ¶¶ 261a-261ll.

263. ArcelorMittal violated the CAA by emitting SO<sub>2</sub> as measured in the combined Plant's boiler exhaust stack in excess of 63 pounds lbs/hr on each of the dates set forth in ¶¶ 261a-261ll.