

United States Steel Corporation Mon Valley Works – Clairton Plant 400 State Street M. S. 71 Clairton, PA 15025

Tel: 412-233-1002 E-mail: mrhoads@uss.com Michael S. Rhoads Plant Manager U. S. Steel Mon Valley Works Clairton Plant

January 11, 2019

Ms. Jayme Graham Air Quality Program Manager Allegheny County Health Department 301 39<sup>th</sup> Street, Bldg. No. 7 Pittsburgh, PA 15201-1891

Via email

Dear Ms. Graham:

RE:

<u>United States Steel Corporation – Mon Valley Works – Clairton Plant</u> <u>Weekly Update Regarding Breakdown Reports #21256, 2157, and 2158</u> No. 2 Control Room, No. 5 Control Room, and Battery Stacks

Pursuant to the Allegheny County Health Department's (ACHD) request, the following is the weekly update regarding the above-referenced breakdowns. This update supplements the Mitigation Plan and updates submitted on January 7 and January 9, 2019.

As we discussed, U. S. Steel is employing significant resources around the clock to investigate the incident. While the investigation is being completed, we have expended and continue to expend substantial personnel and financial resources to employ mitigation efforts to reduce the potential impacts from the incident. We remain committed to employing actions only when such actions can be done in a manner that is safe for our employees, contractors, and the public and when potential impacts to the environment can be minimized. We are glad to have you visit the site today and we would be pleased to have the ACHD re-visit the facility at any time.

## Significant work items completed the week of January 6-12

- 1. Completed planned structural inspections
- 2. 12 1500 HP motors removed and sent for inspection and repair
- 3. Completed gas monitoring system evaluation
- 4. Began installation of additional natural gas jet to Clairton underfire gas system
- 5. Placed order for roof truss fabrication
- 6. Developed safety procedures for removal of axial compressors
- 7. Completed building crane evaluation

## Significant work items planned for the week of January 13-19

- 1. Begin removing piping from axial compressors
- 2. Continue evaluation of existing axial compressors
- 3. Begin installation of one axial compressor
- 4. Place order for building crane electrical components
- 5. Continue installation of additional natural gas jet

Ms. Jayme Graham (ACHD) January 11, 2019 Page 2

- 6. Continue rebuild of lube oil systems
- 7. Continue to procure piping, valves and electrical components.

To date, among other efforts, we have utilized natural gas (displacing coke oven gas) to the extent practicable.

# Previous Mitigation Methods Implemented and Reported week starting January 6, 2019 for SO2 Control:

- 1. Reconfiguration of the natural gas supply system to add additional natural gas supply to No. 1 and No. 2 Boilers at the Clairton facility and No. 1 Boiler and the Hot Strip Mill at the Irvin facility. These facilities are now operating on approximately 80% to 90% natural gas (see table 2 below for updated fuel supply) Complete 1/7.
- 2. Extended coking times on B, C, 13-15, 19, and 20 Batteries (see table1 below). Complete 1/8
- 3. Began hot tap and piping work to prepare for the installation of an additional jet to supply natural gas, which will displace approximately 20 MMCF of coke oven gas, to the underfire system. The underfire gas system supplies all 10 batteries at the Clairton facility. The installation of the jet is estimated to be complete in approximately one to two weeks. Complete 1/8

# **Consideration of Possible Additional Mitigation Steps:**

As we discussed, we understand ACHD's expectation that U. S. Steel consider additional mitigation steps in the event data indicate that such measures are warranted.

We are investigating other mitigation steps to be taken including:

1. Continue to evaluate processes and operations to identify ways to minimize environmental impact and ensure battery integrity and stack compliance.

#### **Operating Data Summary**

Table 1. Summary of coking times, normal vs. current operations.

Battery	Normal Coking Time (hrs)	Previously Reported Coking Times	Current Coking Times		
1	22	22	22		
2	22	22	22		
3	22	22	22		
13	18	21; 21.5	22 (Increased from 21.5 on 1/11)		
14	18	21; 21.5	22 (Increased from 21.5 on 1/11)		
15	18	21; 21.5	22 (Increased from 21.5 on 1/11)		
19	18	22	22.5		
20	18	22	22.5		

Ms. Jayme Graham (ACHD) January 11, 2019 Page 3

В	18	18.5	20		
С	18	18.5	20		

Please note that on January 11, 2019, we increased the coking time on Batteries 13, 14, and 15 from 21. 5 hours to 22 hours as an additional mitigation measure. We continue to monitor the battery and environmental performance.

Table 2. Summary of fuel percentages, normal vs. current operations.

Emission			<del>-</del>					
Units	Normal Operating Fuel Usage			Current Operating Fuel Usage				
		Coke	Blast				Blast	
	Natural	Oven	Furnace	Flow	Natural	Coke Oven	Furnace	Flow
	Gas	Gas	Gas	(MMCFD)	Gas	Gas	Gas	(MMCFD)
Clairton								-
Underfire Gas		100%		90	40%	60%		90
Clairton No. 1								The state of the s
Boiler	13%	87%		25	90-95%	5-10%		25
Clairton No. 2								district or Account of the Control o
Boiler		100%		11	80-90%	10-20%		11
ET Boilers		4%	96%	270	2-3%	2-3%	90-95%	270
ET Blast								Average de la constitución de la
Furnaces	50%	50%		25	100%			25
ET No. 1						ı		
Stove		1-2%	98-100%	38	1%	1%	98-100%	38
ET No. 3								
Stove		1-2%	98-100%	35	1%	1%	98-100%	35
Irvin No. 1								
Boiler	5-10%	90-95%		1.3	90-95%	5-10%	***	1.3
Irvin Hot Strip								
Mill	25%	75%		21	80-90%	10-20%		21
Irvin No. 2								
Boiler	5-10%	90-95%		1.4	90-95%	5-10%		1.4
Irvin No. 3								
Boiler	5-10%	90-95%		0.5	90-95%	5-10%		0.5
Irvin No. 4								
Boiler	5-10%	90-95%	mn	0.5	90-95%	5-10%		0.5
Irvin HPH						**************************************		
Annealing	5-10%	90-95%	***	11	90-95%	5-10%		1
Irvin OCA						***************************************		
Annealing	5-10%	90-95%		1	90-95%	5-10%		1
Irvin								
Continuous								
Annealing	5-10%	90-95%	<b></b>	0.5	90-95%	5-10%		0.5

Ms. Jayme Graham (ACHD) January 11, 2019 Page 4

Irvin No. 1						
Galvanize	100%		0.25	100%		0.25
Irvin No. 2						
Galvanize	100%		0.14	100%		0.14

As noted above, since our January 9, 2019 update, we increased the use of natural gas to offset coke oven gas at the Irvin Hot Strip Mill. In addition, on January 10, 2019, we increased the use of natural gas on Clairton Boiler No. 1. We continue to monitor these efforts.

While we are expediting our efforts to bring the facility back to normal operation, we remain committed to employing actions only when such actions can be done in a manner that is safe for our employees, contractors, and the public; and when potential impacts to the environmental can be minimized.

Also, as has been discussed previously, we remain committed in openly communicating with the ACHD regarding this matter. We appreciate your site visit and we welcome your return to the facility. If you have any questions regarding this update, please contact Mike Dzurinko or me.

Sincerely,

Michael S. Rhoads

Millsell

cc: Jim Kelly (ACHD)

Jason Willis, Esq. (ACHD)

Mike Dzurinko (USS)

Chip Babst, Esq. (Babst Calland)

Mike Winek, Esq. (Babst Calland)

David Hacker, Esq. (USS)